■S25C黒 プラント, 工場設備, 20K蒸気配管設備 継手



■SS400黒

JIS20K 防災設備(消火設備) ねじ込み相フランジ(サイズ一覧)


品名/サイズ	1/2	3/4	1	11/4	11/2	2	21/2	3	4	5	6
黒 20K PT 相フランシ゛	0	0	0	0	0	0	0	0	0		

○印・・・標準品

■黒 STPG370シームレス材 プラント・防災設備 パイプニップル(サイズ一覧)

品名	サイズ	1/8	1/4	3/8	1/2	3/4	1	11/4	11/2	2	21/2	3	4	5	6
黒短(バレル)ニップル S/8	80, S/40		0	0	0	0	0	0	0	0					
長さ(最少)			26L	28L	34L	38∟	42L	50∟	50∟	58L					
	X50L		0	0	0	0	0	0	0						
黒	X65L		0	0	0	0	0	0	0	0					
	X75L		0	0	0	0	0	0	0	0					
丸ニップル	X100L		0	0	0	0	0	0	0	0					
S/80	X125L		0	0	0	0	0	0	0	0					
	X150L		0	0	0	0	0	0	0	0					
	X200L		0	0	0	0	0	0	0	0					

〇印•••標準品



品名	90E	45E	ストエル	TEE	FC	CAP	OU	BU	6角N	HC	BOSS	45BOSS	PL	UG
サイズ	PT,SW	PT,SW	PT	PT,SW	PT,SW	PT,SW	PT,SW	PT	PT	PT,SW	PT,SW	PT,SW	6角	4角
1/8	0	0	0	0	0	0	*		0	*	*		0	0
1/4	0	0	0	0	0	0	0		0	0	0	*	0	0
1/4×1/8	0			0	0			0	0					
3/8	0	0	0	0	0	0	0		0	0	0	*	0	0
3/8×1/8				*	*			0	0					
3/8×1/4	0			0	0			0	0					
1/2	0	0	0	0	0	0	0		0	0	0	0	0	0
1/2×1/4				0	0			0	0					
1/2×3/8	0			0	0			0	0					
3/4	0	0	0	0	0	0	0		0	0	0	0	0	0
3/4×1/4				*	*			0	0					
$3/4 \times 3/8$				0	0			0	0					
3/4×1/2	0			0	0			0	Ō					
1	0	0	0	Ō	Ō	0	0		ō	0	0	0	0	0
1 × 1/4			Ť	*	*			0	Ō					
1 × 3/8				O O	Ö			0	ō				 	
1 × 1/2	0		1	0	Ö			0	0					
1 × 3/4	0			0	Ö			0	ō			\vdash		
11/4	0	0	0	Ö	Ö	0	0	<u> </u>	Ö	0	0	*	0	0
11/4×3/8			<u> </u>	*	0	⊢	- <u>`</u> -	*	*	<u> </u>	<u> </u>	 	─ ──	
$11/4 \times 1/2$			1	Ô	0			Ô	Ô			\vdash	 	
$11/4 \times 3/4$	0			 	Ö			0	0			\vdash		<u> </u>
11/4×3/4 11/4×1	0		 	0	Ö	 	 	0	0			\vdash		
11/2	0	0	0	0	6	0	0	_ 	0	0	0	*	0	0
11/2×1/2			\vdash	0	0	\vdash	 	*	*	 	\vdash		$\vdash \check{-}$	$\vdash \vdash$
$11/2 \times 1/2$ $11/2 \times 3/4$		 		0	0	 	 	0	0			 		
11/2×3/4 11/2×1	0			0	0			0	0			 		
11/2×11/4	0			0	0			0	0			 		
2	0	0	0	0	0	0	0	$\overline{}$	0	0	0	*	0	0
2×1/2	0		\vdash	0	0	\vdash	-	0	0	<u> </u>	\vdash	<u>~</u>		
$\frac{2 \times 1/2}{2 \times 3/4}$	0			0	0			0	0			 		
2×1	0			0	0		 	0	0			 		
2×11/4	0		 	0	0		 	0	0	 		 		
2×11/4 2×11/2	0				0			0	0			 		
21/2	0	0		0	0	O丸	0	$\overline{}$	0	*	0	 	0	0
21/2 21/2×3/4	\vdash			0	0	₩	~	0	*	<u>~</u>	\vdash	 		
$\frac{21/2 \times 3/4}{21/2 \times 1}$				0	0			0	*			 		
$21/2 \times 1$ 21/2 × 11/4					0			00	* *			 		
$\frac{21/2 \times 11/4}{21/2 \times 11/2}$				0	0		 	0	* *	 		 		
$\frac{21/2\times11/2}{21/2\times2}$				0	0			0	*			 		
3	0	0		0	0	O丸	0		0	*	0	 	0	0
3×1				0	0	UXL		0	*	*	\vdash	 		
3×1 3×11/4		ļ———	-	0	0		 		* *			 		
3×11/4 3×11/2		ļ———						0	* *			 		
3×11/2 3×2		 		0	0		 	0				 		
			ļ	0	0		<u> </u>	0	*	<u> </u>		 		
3 × 21/2		\\	—	0	0	W.T.	 	0	*			\vdash	V/ C #	\Box
4	0	*	ļ	0	0	※丸			0	*	*	 	※8角	0
4 × 3/4			!	0	0		 	0	<u> </u>	<u> </u>		 		
4 × 1			ļ	0	0			0	<u> </u>			 		
4×11/4				0	0		ļ	0	<u> </u>	 		 		
4×11/2			ļ	0	0		 	0		L		 		
4 × 2				0	0			0						
4 × 21/2				0	0		 	0						
4 × 3				0	0			0						

〇印・・・標準品 ※印・・・都度対応となります <mark>弊社高圧管継手は</mark>20K継手相当品として<mark>使用出来ます</mark>

